



8a	8b	9a	9b		
x1	x1	x1	x1		
10					
x2		x2			
14	15		16		
x2	x2		x4		
20	21	22	23	25	29
x1	x1	x2	x3 Ø4×20	x2	x 1
30					
x 1					
31	32	39	41	42	43
x2	x1	x1	x4 M5×20	x8 M6×20	x6 M6×30
44	45	46	47	48	51
x2 M6×24	x6 M6×16	x 6 Ø7 / Ø30	x 1 Ø4×40	x 4 M6×25	x 2 Ø6×80 PH


1





2



3





3

~ 35mm

~ 35mm

90°

51 2x

20 mm

X

Min $\varnothing 8 \times 40 \text{ mm}$

20 mm

Min $\varnothing 6 \times (X + 50) \text{ mm}$

!




51

x 2


!

51


x 8






7




8







12







13









14







19



I



II



III

